

Office of The Executive Engineer, Provl. Divn. PWD B&R Bathinda

Third Floor, Distt. Administrative Complex, Bathinda

Ph. No. 0164-2212878, E-mail ID-xenbtiprov1@gmail.com

APPENDIX - XI

**BUILDING SAFETY
CERTIFICATE**

No:-

2530

Dated:

05/06/2020

Certified that the existing building..... **Silver Oaks Global School**, ... (name of the building or premises) at....**Sushant City-II, Bathinda**(address) comprise of...0...basement (s)3...upper floors) owned/ occupied by.....**Silver Oaks Global School** ...(name of the Institution) appears to be safe by visual inspection as verified by the officers concerned of**PWD (B&R)**.....(Name of Department/ Govt.) on...**02.06.2020**.....(date of inspection) in the presence of.....**Principal**.....(name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy with effect from....**01.04.2020**.....for a period of.....**one**..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The School will ensure that the District Fire Officer Bathinda will issue the Fire safety certificate for the school upto the period of issuance of this certificate.
- 2.
- 3.
- 4.

Vaild upto31.03.2027.....by

* Strike out whichever is not applicable.


Executive Engineer,
Provincial Division PWD B&R
Bathinda.



ਵੱਲ

PRINCIPAL,
Silver Oaks Global School,
Sushant City-II, Bathinda.

ਨੰ: 2530 ਮਿਤੀ: 05/06/2026
ਵਿਸ਼ਾ: ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ- Silver Oaks Global School, Sushant City-II, Bathinda.

ਹਵਾਲਾ: ਆਪ ਦੇ ਦਫਤਰ ਦਾ ਪੱਤਰ ਨੰ. SOGS/SC-2/2026-27/Off/004 ਮਿਤੀ. 18.04.2026
ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅੰਕਿਤ ਇਮਾਰਤ ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਸਾਲ 2026-27 ਲੈਣ ਲਈ ਆਪ ਵੱਲੋਂ ਇਸ ਦਫਤਰ ਵਿਖੇ ਪ੍ਰਾਪਤ ਹੋਇਆ ਹੈ। ਆਪਦੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੀ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਦੇ ਦਫਤਰ ਵੱਲੋਂ ਵਿਜ਼ੁਅਲੀ ਇੰਸਪੈਕਸ਼ਨ ਕੀਤੀ ਗਈ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ/ਸਿਫਾਰਿਸ਼ ਅਨੁਸਾਰ ਨਿਮਨਲਿਖਤ ਨਿਰੀਖਣਾਂ ਅਤੇ ਸ਼ਰਤਾਂ ਅਧੀਨ ਸਾਲ 2026-27 ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 31.03.2027 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

1. ਸਕੂਲ ਕੋਲ ਕਿਸੇ ਅਣਸੁਖਾਵੀਂ ਘਟਨਾ ਨਾਲ ਨਜਿੱਠਣ ਲਈ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ ਦੌਰਾਨ ਬੱਚਿਆਂ ਨੂੰ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਸੁਰੱਖਿਅਤ ਬਾਹਰ ਕੱਢਣਾ ਅਤੇ ਸਬੰਧਤ ਵਿਭਾਗ ਨਾਲ ਤਾਲਮੇਲ ਕਰਨ ਦੀ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ। ਸਕੂਲ ਨੂੰ ਇਸ ਯੋਜਨਾ ਦੀ ਪ੍ਰਭਾਵਸ਼ੀਲਤਾ ਨੂੰ ਯਕੀਨੀ ਬਣਾਉਣ ਲਈ ਨਿਯਮਿਤ ਤੌਰ ਤੇ ਸਮੀਖਿਆ ਅਤੇ ਅੱਪਡੇਟ ਕਰਦੇ ਰਹਿਣਾ ਚਾਹੀਦਾ ਹੈ।
2. ਜੇਕਰ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਕੋਈ ਵਾਧਾ, ਤਬਦੀਲੀ, ਵਿਸਤਾਰ ਅਤੇ ਸੋਧ ਦੀ ਲੋੜ ਹੈ ਜਾਂ ਕੀਤੇ ਜਾਣੇ ਹਨ ਤਾਂ ਇਸ ਦਫਤਰ ਦੀ ਤੁਰੰਤ ਜਾਂਚ ਦਾ ਪ੍ਰਬੰਧ ਕੀਤਾ ਜਾਣਾ ਚਾਹੀਦਾ ਹੈ ਅਤੇ ਉਸ ਹਿੱਸੇ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫਤਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ ਜਾਵੇ।
3. ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀਆਂ ਕੰਧਾਂ, ਨੀਹਾਂ ਅਤੇ ਛੱਤਾਂ ਕੁਦਰਤੀ ਆਫਤ ਜਾਂ ਕਿਸੇ ਹੋਰ ਕਾਰਨ ਕਰਕੇ ਬੈਠ ਜਾਣ ਤਾਂ ਇਸ ਸੂਰਤ ਵਿੱਚ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਦਫਤਰ ਨੂੰ ਤੁਰੰਤ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰੰਤ ਹੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਰਤੋਂ ਵਿੱਚ ਲਿਆ ਜਾਵੇ।
4. ਸਬੰਧਤ ਵਿਭਾਗ ਤੋਂ ਵੱਖਰੇ ਤੌਰ ਤੇ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ, ਇਲੈਕਟ੍ਰੀਕਲ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਪ੍ਰਾਪਤ ਕੀਤਾ ਜਾਵੇ।
5. ਬਿਲਡਿੰਗ ਦੀ ਸੇਫਟੀ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੇਅਰ ਕਰਵਾਉਣ ਦੀ ਜ਼ਿੰਮੇਵਾਰੀ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਦੀ ਹੈ। ਇਸ ਰਿਪੋਰਟ ਦੇ ਬਾਵਜੂਦ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਸਾਰੇ ਪੱਖਾਂ ਤੋਂ ਬਿਲਡਿੰਗ ਦੀ ਸੁਰੱਖਿਆ ਲਈ ਜ਼ਿੰਮੇਵਾਰ ਹੈ।
6. Vikas Bansal & Associates, Bathinda ਵੱਲੋਂ ਆਪਣੇ ਪੱਤਰ ਨੰ. VBA/SOS/SSC/02 ਮਿਤੀ 16.04.2026 ਰਾਹੀਂ ਸਟਰੱਕਚਰ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਦਿੱਤਾ ਗਿਆ ਹੈ ਅਤੇ ਉਨ੍ਹਾਂ ਦੇ ਸਰਟੀਫਿਕੇਟ ਅਨੁਸਾਰ ਸਕੂਲ ਸੈਸ਼ਨ 2026-27 ਲਈ ਵਰਤੋਂ ਲਈ ਸੁਰੱਖਿਅਤ ਹੈ, ਪ੍ਰੰਤੂ ਇਸ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰਮਾਣ ਇਸ ਵਿਭਾਗ ਵੱਲੋਂ ਨਹੀਂ ਕੀਤਾ ਗਿਆ ਹੈ, ਇਸ ਲਈ ਇਸ ਵਿਭਾਗ ਦੁਆਰਾ ਬਿਲਡਿੰਗ ਦੀ ਸਟਰੱਕਚਰ ਦੀ ਸੇਫਟੀ ਖਾਸ ਕਰਕੇ ਭੂਚਾਲ ਦੇ ਦ੍ਰਿਸ਼ਟੀਕੋਣ ਤੋਂ ਯਕੀਨੀ ਨਹੀਂ ਬਣਾਈ ਜਾ ਸਕਦੀ ਹੈ।
7. ਸਕੂਲ ਸਟਾਫ ਮੈਂਬਰਾਂ ਨੂੰ ਉੱਚਿਤ ਸੁਰੱਖਿਆ ਸਿਖਲਾਈ ਪ੍ਰਦਾਨ ਕਰਨੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ, ਫਸਟ ਏਡ ਅਤੇ ਨਿਕਾਸੀ ਪ੍ਰੋਟੋਕੋਲ ਨੂੰ ਸੰਭਾਲਣ ਦੀਆਂ ਪ੍ਰਕਿਰਿਆਵਾਂ ਵੀ ਸ਼ਾਮਲ ਹਨ।
8. ਬਿਲਡਿੰਗ ਦੇ ਕਵਰਡ ਏਰੀਏ ਦੇ ਹਿਸਾਬ ਨਾਲ ਜੀ.ਆਰ.ਨੰ. 358402 ਮਿਤੀ.11.05.2026 ਰਾਹੀਂ ਵੀਹ ਹਜ਼ਾਰ ਰੁਪਏ (20,000/-) ਬਿਲਡਿੰਗ ਨਿਰੀਖਣ ਫੀਸ ਵਜੋਂ ਜਮ੍ਹਾਂ ਕਰਵਾ ਦਿੱਤੇ ਗਏ ਹਨ।
9. ਇਹ ਰਿਪੋਰਟ ਕਾਨੂੰਨੀ ਉਦੇਸ਼ ਲਈ ਵੈਲਿਡ ਨਹੀਂ ਹੈ।
10. ਸਕੂਲ ਦਾ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ 01.04.2029 ਤੱਕ ਵੈਲਿਡ ਹੈ। ਜਿਸ ਦੇ ਆਧਾਰ ਤੇ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 31.03.2027 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਨੱਥੀ/ਨਕਸ਼ਾ

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਨੰ.1 ਭਤੇਮ ਸਾਖਾ ਬਠਿੰਡਾ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ: 132 ਮਿਤੀ: 02.06.2026 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਿਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਤਕ ਮੰਡਲ ਭਤੇਮ ਸਾਖਾ,
ਬਠਿੰਡਾ।
ਮਿਤੀ:

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਤਕ ਮੰਡਲ ਭਤੇਮ ਸਾਖਾ,
ਬਠਿੰਡਾ।

APPLICATION FOR SCHOOL BUILDING SAFETY CERTIFICATE

FOR THE YEAR 2026

Name of the School : SILVER OAKS GLOBAL SCHOOL
Location : SUSHANT CITY-II, MANSA ROAD, BATHINDA
Plot Area : 4.07 ACRE
Plinth Area : 9415 Sq mtr
No of Stories : 3
Year of Construction of : 2014

If the building has been constructed under
the supervision qualified Engineer, the

Following details may be give

- a) Name of the Engineer : Mr. VIKAS BANSAL (B.ARCH)
- b) Address of Engineer : SCO-24 CITY PLAZA MARKET, HANUMAN CHOWK, BATHINDA
- c) Set of structure drawing used in Available : MAP ATTACHED HEREWITH
- d) Whether the building has been constructed :

Purpose of

- a) School Yes / No
- b) Residential purpose Yes / No
- c) Converted for use Yes/No

Material used for roofs:

- a) R.C.C. Slab : Yes/ No
- b) R.S. Joints & Battens : Yes/No
- c) Wooden Joints & Battens : Yes/ No

Material used for Walls:

- a) Mud motor : Yes/No
- b) Cement Mortot : Yes/No
- c) Plaster: Lime Mortar :Yes/No



Flooring:

TILE FLOORIN

a) Brick Paving

(Yes/No) ✓

A Detailed drawing indicating dimension of the rooms & locations of doors and window is attached.

12. General :

1.) In case of Double story building 1.5 meter

(Yes/No) ✓

2) Width upstairs are constructed or not

3) Whether all class room are provided to door system

(Yes/No) ✓

Whether fire safety measures have been

(Yes/No) ✓

adopted and are in working condition

For Silver Oaks Global School

Auth. Signatory

Dated: 18.04.2026

Signature and stamp of the head of institution

PART- II

(For the Use of PWD B & R department)

A) I ES Anurag Chaudhary S.D.E. along with Kishore Kumar J.E. have visited this school on 02/06/2021 and have inspected it from all angles of safety and found it fit for normal use as school Building.

B) If in any case addition or alteration extension or modification of this building is to be carried out, it should be carried out under the supervision of technical qualified Engineer and after its Completion, this certificate may again be obtained from undersigned.

C) In case buildings are effected by flood or if there is settlement to walls foundations, edging or roof, immediate inspection the undersigned arranged to check the stability and safety of the building.

D) The Building can be safely occupied for normal use upto 31/03/2027.

E) Inspection fee has been deposited by the school vide G.R. No. 358402 Dt. 11/05/2021 amounting to Rs. 20000/-.

Countersigned

Executive Engineer

Sub Divisional Engineer
Sub Divisional Engineer
Prov. Sub Divn. No. 1, PWD B&R
Bathinda

